

School – The Kings School, Parramatta - Case Study

OTHER SERVICES AVAILABLE...

- New Clock installations, including GPS synchronised mechanisms
- Tower Clock Restorations & Repairs
- Manufacturing parts for existing time pieces
- Bell Restorations
- Service and Maintenance Agreements on existing clocks
- Bell Strikers
- Authorised Installer of Simplex Time Control Equipment

The clock in the 'hay shed' on the school sports field had been stopped for many years. The mechanisms had suffered from a lack of maintenance, a build up of dust and not least of all, an accumulation of cobwebs and insect activity.

When the old mechanisms were removed it was found the original steel dials had rusted and their lower sides had rotted away.

New aluminium dials were manufactured along with new hands to suit and a new 'look' was adopted better suiting the architecture.

Four Bodet GPS mechanisms were used for the installation and were fitted inside weather resistant enclosures to prevent any future interference by insect activity.

The new installation requires no setting by the school staff and has been well received.



Bodet

Since the company was created in 1868, automatic bell ringing systems and tower dials have been built in respect of the patrimony.

The company Bodet established itself as the reference brand thanks to its long experience. Our constant development enables us to provide innovating and modern solutions with respect for traditions and patrimony :

- Wooden belfries and yokes restoration
- Restoration of worn-out or cracked bells
- Tower dials
- Automatic bell ringing systems
- Master clocks
- Tower clock movement

Bodet provides :

- The experience of the first European producer of tower clocks
- A renowned know-how
- A specialized Research and Development department
- Installations in compliance with safety standards
- A quality performance guaranteed by the ISO 9001 approval

Refer: www.bodet.com

Installation and benefits

The intelligent clock movement with direct FI/DCF or GPS synchronisation offers an easy installation (no master clock) and an absolute reliability and accuracy.

This ensures that the dials re-set automatically after a power outage (once power is restored) and also automatically adjust for daylight savings. This is especially useful in areas where the power supply can be unreliable.



TOWER CLOCK SERVICES AUSTRALIA
MANUFACTURING HOROLOGIST... ..SPECIALISING IN TOWER CLOCK,
INSTALLATIONS, REPAIRS AND MAINTENANCE
BELL RESTORATIONS

PO Box 281
Wyong NSW 2259
ABN: 47014201410

Mobile: 0427 312 334
Phone: 02 4353-7079
E-mail:
tim.tracey@towerclock.com.au
www.towerclockservices.com.au